

Diamond Drilling



41105SE0039 0011C1 NAIRN

010

Township of NAIRN

Report NO: 15

Work performed by Sundun Mining Co. Limited

Claim NO	Hole NO	Footage	Date	Note
S 155667	1	54.0'	Oct/70	
	2	99.0'	Oct/70	
	3	104.0'	Oct-Nov/70	

---


TOTAL: 3 DR 257 FT

Notes:









HOLE-NO-I : 250 ft. SOUTH + 50 ft. EAST OF NO. 4 POST

Depth- 54ft, Dip-60°, AZIMUTH- 00 Deg. & 00 minutes

HOLE-NO-2.- 254 ft. SOUTH + 50 ft. EAST OF NO. 4 POST


Depth- 99ft, Dip-56°, AZIMUTH- 180 Deg. & 00 minutes

HOLE-NO-3 : 250 ft SOUTH + 150 ft. EAST OF NO. 4 POST

Depth- 104ft., DIP -45°, AZIMUTH- 00 Deg. & 00 minutes

LOT-10

LOT-9



HOLE-NO-1 : 250 ft. SOUTH + 50 ft. EAST OF NO. 4 POST  
 Depth- 54ft, Dip-60°, AZIMUTH- 00 Deg. 40 minutes  
 HOLE-NO-2.- 254 ft. SOUTH + 50ft. EAST OF NO. 4 POST  
 Depth- 99ft, Dip- 56°, AZIMUTH- 180 Deg. 40 minutes  
 HOLE-NO-3 : 250 ft SOUTH + 150 ft. EAST OF NO. 4. POST  
 Depth- 104ft., DIP -45°, AZIMUTH- 00 Deg. 40 minutes

Data - Road  
 Creek

